



AM General Headquarters “Home of the Hummer”



**FIRST
RESPONSE**
© Disaster Restoration Specialists



A fire in the HVAC system caused extensive smoke odor throughout the entire AM General office facility. In addition to the odor much of the contents and structure suffered soot damage.

Emergency Mitigation Teams from First Response were able to clean, deodorize and restore the damage in a matter of days, allowing the production of the famous Hummer to continue without interruption.
